G. R. S. 59] GPB - 15,000 20 12 13

GENERAL AND REVENUE SECRETARIAT.

1899-1900.
~~191~~.
(Munzai)

File No. 6

Selection I

Serial Nos. 1-16

Papers Filed.

Month April 1900

SUBJECT.

File relating to the repairs of the Sri Kallesvara Varadaraja Swamy Temple buildings at Marekalli Village, Mala Valli Taluk.

PREVIOUS REFERENCES.

LATER REFERENCES.

Munz 7 247 of 1905

THE MUZRAI SUPERINTENDENT'S

OFFICE.

NOTE.

SUBJECT. Repairs to the
The building of the
Sri Lakshmi Nara-
-sinha Swamy Temple
at Marekalli Village
Kalavalli Taluk.

GPB—1,000—10-10-12

MUZARAYI.

(General Serial No. 30.)

189 3.

From [illegible] Sl/

To The Dy Com[illegible] Mysore Dy

Dated 13

Despatched 14 July

Received

Enclosures No.

General No. 48

~~*Muzarayi E. No.*~~

I have the honor to refer the Dy Com[illegible] Lr No 606 (dated 6th Sept 1892) forwarding the Representation at the Dussera Assembly held in Oct 1892. and to request the submission of a report thereon together with an estimate for the requisite repairs on or before the 15th August 1893

By order

A[illegible]

Sec[illegible]

Also Same No 207 dt 4-9-93
Also Same No 32 dt 2-10-93
From the same No 46 dt 13/10/93

Murray

(General Serial No. 30.)

189 .

From SLL

To D.C. Mysore.

Dated 2 ~~29~~ Oct

Despatched 3rd ~~Sept~~ /93.

Received

Enclosures No.

General No. 327 R
No.

This Office Nos 48 ~~of 13~~ 13th ~~only~~ and 207 dy 4th ~~Sept~~ /93 requesting the submission of a report with an Estimate for requisite repairs to Marehalli Narasimhaswamy Temple.

Has the honor to draw his attention to the above & request a very early reply thereto.

B.O

for Secy.

From the Same No 488 9/13/93

Ref-
No. 348

MYSORE DEWAN'S OFFICE.

PETITION DEPARTMENT.

OFFICIAL MEMORANDUM.

Sl 3

The accompanying Petition No. 527

dated 14th August/93 received at the Dewan's Office from Archi Subramiah and others of Marenhalli, Malavalli Taluk, Mysore District, praying for repairs to the temple of Sri Lakshminarasimhaswamy of their village

is forwarded, ~~together with its enclosures,~~ to the Mmzrai Secretary

Dewan

BANGALORE, 28th August 1893.

M. G. C. P. Bangalore.—17.

To D.C. Mysore No 2259 9/9/93

MUZARAYI.

(General Serial No. 30.)

1893.

From SLG

To The Dy Commr
Mysore Dist

Dated 9th September 93

Despatched 12 "

Received

Enclosures No. 1

General No. 225

Muzarayi. F. No.

Has the honor to forward herewith petition No 527 dated 14th Augt 93 from Subbaraya and other devotees of the temple of Sree Lakshmi Narsinhaswami at Marshalli in the Malvalli Talk praying that orders may be issued for the repairs of the temple and to request that an estimate for the necessary repairs of the Institution may be prepared & submitted

the same vide 4389/31/10/93

submitted to this
at an early date.

2. The Dy Commr is
also requested to report
what portion of the
estimated cost of repairs
will be contributed
by the petitioners and the
Community interested
in the preservation of the
temple.

By order

Secretary
G.V.

OFFICE OF THE DEWAN OF MYSORE
324
MUZRAI BRANCH

(General Serial No. 30.)

189

From The Deputy Commissioner Mysore District SRS

To The Muzrai Secretary to the Dewan of Mysore

Dated 13th October 1893

Despatched

Received 14-10-93

Enclosures No. 2 & one file

General No. 468.
No.

Forwarding copy of the Periach Rocks Sub Division officers no 175 dated the 22nd August. regarding the repairs to Hanchalli Narasimha-Swamy temple &c

14-10

the same no 4388 of 31/10/93

No. 468

DEPUTY COMMISSIONER'S OFFICE,
MYSORE DISTRICT,

Dated Mysore 13th October 1893.

From

A Rangasawmy Iyengar Esquire
Deputy Commissioner,
Mysore District.

To

The ~~*Chief*~~ *Secretary to the Dewan of Mysore,*
Bangalore

SIR,

With reference to your docket no 48 dated 13th July 1893 requesting the submission of a report together with an estimate for the requisite repairs to Mare halli Narasimha Swamy temple, I have the honor to forward for your information Copy of the French Rocks Sub Division officers no 175 dated the 22d August with enclosures (to be obligingly returned) from which it will be seen that the repairs have been estimated to cost about Rupees 10,504. I beg also to forward in the same connection a Muchalika dated 16th September 1893 since received from the Sub Division Officer in which the inhabitants of Malavally have promised to contribute 1/4 Cost of the estimate It is diffecult to say whether the people will

to them promise after the
project is sanctioned. The Temple is double
one worth repairing and the needful will
have to be done when the question of funds
is disposed of by Government.

I have the honor to be
Sir
your most obedient Servant

Asst
Dy Commissioner
Myaree District

Compd.
Tisa.

From.

The Sub Division officer
French Rocks.

To

The Dy Commissioner
Improvement

Dated 22d August 1893.
No 175.

His docket No 44 dated 9th instant requesting the submission of a report on the repairs to the temple of Varasimhaswamy of marehalli together with an estimate.

In reply has the honor to submit herewith an estimate amounting to Rupees 10504 together with the malavally Amildars report and also the petitions received from the villagers on the Subject.

I further beeg to state that the temple seems to be an ancient one, and as it has no funds available for the repairs, provision will have to be made from General Savings. It is however advisable to have the estimate thoroughly revised

by professional men and
the undersigned hopes to be able to induce
the petitioners and other devotees of the
temple to contribute their quota in a
liberal manner when the estimate is
completely prepared for submission to the
Government for sanction.

/Signed/ S. Perumalla Rao
offg: Sub Division officer
French Rocks

"Copy"

Manamunj
Dy. Commissioner
Pondicherry

Compd
Ulu

to this office at
an early date.

3. The Contributions promised by the devotees and the inhabitants of Malavalli should be recovered at once and credited to Temple.

4. The enclosures are herewith re-turned

By order
A1
Secretary

This draft
Compl.d

MUZARAI.

(General Serial No. 30.)

1893. SL6

From

The Secretary to the Dewan
of Mysore

To The Deputy Commr
Mysore Distt

Dated 31 Oct

Despatched 1st Nov 93

Received

Enclosures No. 1 to file No.

General No. 438
Muzarai F. No.

His letter No. 468 of the 13th instant for-warding the papers connected with the repairs of the Sree ~~Lakkhmi~~ Lakshmi Narasimha Swami Temple at ~~Malavalli~~ Maréhalli in the Malavalli Taluk

Referring to the above has the honor to observe that the temple has no funds at its credit, that the Estimated

Mysore Govt. Central Press, Bangalore. ~~25-9-93-1,000.~~

estimated cost of its repairs amounts to Rs 10,504/- that the inhabitants of Malavalli have executed a Mutchilika on a plain paper promising to contribute only ¼ of the estimated cost, that the estimate now submitted was not prepared by a professional man and that it requires a thorough revision, as provision is made therein for some unnecessary repairs also

2. The Dy Commr is therefore requested to have a revised estimate prepared by a professional man for only such repairs as are immediately necessary and to submit the

Sam

1899 887

From The Supervisor No: 2.
Sub-Division D.P.W. Mandya
French Rocks Division

To The Munzaray Secretary
to the Government of Mysore
Bangalore

Dated 28th August 1899.

Despatched

Received

General No.
No.

Enclosure No. 1. Estimate
1. Report

Sir,

I beg to submit herewith an Estimate with report amounting to Rs 763. for improving and repairing the Marabally Sree-Lakshmy Narasimaswamy Temple Malvelly Taluk as personally directed, and to request that you would be so good as to kindly sanction the Estimate at your earliest convenience with a view to complete the works soon.

2. I beg to recommend that Mr Krishna Rao

Vide no 236 d/31/8/99

OFFICE OF THE DEWAN OF MYSORE
RECEIVED
Date 28-8-99
REG. No 726
MUZRAI BRANCH

Malavelly Jakeh may be requested to Carry out the works under his direct Supervision with the help of Sub-Overseer N. Vydinatha Iyer of my Department. I shall be happy to inspect this work as often as possible and give timely while the works in Progress. Our Thanniechalam Moodliar Contractor of this Department has been ordered to Carry out the ordinary works such as dismantling partition walls &c as personally directed

Have to remain
Sir,
Your most obedient Servant

S. Viswanathan

Supervisor No 3.
Sub-Division

Aff

Report Accompanying the Estimate for Improving and Repairing the Maravally Sri-Lakshmy Narasimaswamy's Temple Malvelly Taluk.

Reference.

The Dewan's personal orders on the 16th of August 1899.

Report

This is an Ancient, important and famous temple, situated at a distance of two miles from the town of Malvelly. Many pilgrims resort to this temple Annually during festivals besides the local people that worships daily. The temple as it is, is ill-ventilated to such an extent that one cannot see and worship the Deity even standing closely. Himself the keep of the Lantern lights and besides the whole temple and more specially the most inner part of it (Girpagraham) is in fact a regular dwelling place for Bats which not only attack the people directly they enter into the temple but also smells the whole place very dirty and un-wholesome

The enclosed Estimate is prepare

providing therein all the urgent and necessary works on the line of instructions issued personally by the Munzaroy Secretary at the Spot with a view to throw sufficient light into the Girpagraham and else where and to demolish all the unsightly partition walls in the inner part of the Temple and the outside Prakaram as well to render the whole Temple fit for human beings to worship the Deity.

The items of work so estimated for, are as follows:—

(1) Dismantling the roof of the Ardha Mandapam Longitudinally (21'×7') including the end walls between the Sugnasi Mandapam and the Main one which fortunately throws not only a lot of light and air but it is also a very great convenience for the people to easily get into the Girpagraham for the purpose of worshiping the Deity from the entrance once to go out as well through the other without interfering with the people that may be assembled in the Main Mandapam especially during the Drainage operations

(2) providing two puckka and strong

doors

doors Made of teak wood with iron fittings and Lock Complete, One for the Girpragaham and the other in the left Pradakshana Mandapam near the drain, As the existing door at the latter place is very weak and defective for a temple of this Class. Another Jungle wood door is also provided in the estimate for the Cook room.

(3) Building a brick Masonry retaining wall Around the drain for a length of 164 feet to a height of 2 feet including Coping which is Absolutely Necessary for the proper drainage of water without damaging the Pradakshana Mandapam. Provision is also Made for Constructing a proper drain with Covering Slabs at top flush with the existing floor, to drain off all this water outside the temple.

(4) Two New cut Stone pillars are provided for, in the estimate for the Supports of the Stone beam in front of Namaskaram, which is badly Cracked.

(5) By the improvements Suggested under the first Item, the Cachkaram

with the Roof-gutter open and it is very desirable and Absolutely Necessary to have Something at top in the way of frame work with strong iron bars to prevent Crows and other birds from entering into the temple on the Marriage and other occasions and to Chiefly prevent the Thieves from entering into the Temple at Nights on the occasions Mentioned above.

(6) A Sum of Rupees twenty for each, is provided for building a proper Sky light hall for the Yagasala and Mandapaly buildings which are Absolutely Necessary both for light and Air and to Chiefly Avoid Any dirt of the Bats Creeping into the Cooked food un-Knowingly which are not improbable under the existing Arrangements.

(7) Provisions are also made for repairing the Cement floor and building parapets on the top of the temple at the flight of steps, which the Caller, are necessary for the safety of the people and Children that go on the top of the temple and for decency

decency of the building as well.

'8) Provision for fixing a teak wood window (3'×4') with iron bars between the flight of steps leading to the top of the temple and the main door, is also made to throw light and air into the Pradakshina Prakaram.

All the above mentioned improvements and repairs are very essential which are therefore to be carried out to render this important temple fit to be worshiped. Reasonable rates are entered in the estimate Considering the value of the works to be Carried out.

[signature]

Supervisor No 3.
Sub-Division

A.H.

Drawn
24/1/11

Detailed Estimate of Repairing the Hirahally Narasimhaswamy's Temple. Malvally Taluq Mysore District.

Sub Head	Details of work	No:	Dimensions L	B	D	Contents	S & C
Dismantling Brick and Stone Walls.	Girpagraham:-	Sarbhagrathem					
	Cross walls inside of Sngu-Nasi Mandapam	2	3	1½	7	63	
	Cross walls Inside —	2	10	1½	7	210	
	Side Verandah —	1	10	3	3	90	
	Concrete over the roof of one Ankanam Lengthwise	1	21	7½	3	472½	
	Retaining wall round the Dram on side of Sngunasi & Girpagra-ham	1	106	1½	2	318	
	Covering of the Dram Left-Pratha Kshana Mandapam	1	24	5	2	240	
	Verandahs between Cook Room and Bashiachar, Yagasalai and Namalwar Seats —	2	25	6½	3	975	
	Side walls of Bashiachar	2	6¾	1½	10	202½	
	Front ✗ wall of — Dº —	1	3½	1½	8	42	
	Side walls of Bashiachar	2	6	1½	6	108	
	Front wall of — Dº —	1	8	1¼	8	80	
	Platforms of Bashiachar & Namalwar	2	10	6	1½	180	
	Side walls of Verandah room	1	10	1½	8	120	
	Front wall —	1	6	1½	6	54	
	Vynayakan Mandapam	1	3	2	6	36	
	Walls in the Sngunasi	2	8	2½	7½	300	
	Door Ways in — Dº —	1	2½	1½	7½	28	
	Broken wall at the entrance of Steps Leading to Gps of room	1	1½	1	8	12	
	Total Dismantling C feet					3531	353

Excavation.	Foundation for the Drain to Drain of the rain water and Abishaca water from the Temples	1	15	1	2/3	
	Total cy Ds					
Brick in chunam	Retaining wall round the Drain Out-Side of Sngunasi	1	104	1 1/8	1 3/4	204 3
	Filling foundation for the Drain within the Pratha -Kshna Mandapam	1	30	2 3/4	1/2	41 1/4
	Out-Side of - Do - for 15 ft Length	1	15	2 3/4	1/2	20 5/7
	Side walls of the Drain	2	45	3/4	3/4	50 5
	Covering Courses -	1	45	2'	1/2	56 1/4
	Platforms for Placing the Bashiachar & Namalwar	2	14	1'	1	31 1/2
	Seats of — Do —	2	3	2	1/2	6
	Verandah Retaining wall in front of Cooking Room	1	8	1 1/8	2	18
	Front wall of Prathakshna — ha Mandapam left Door	1	8	1 1/2	8 1/2	102
	Partition walls in the Sngunasi Mandapam	4	2 1/4	2 1/4	7	141 3
	Backing up the face of open Space from bottom of roof to top of — Do —	1	50	1'	3	168 3/4
	Above roof Level —	1	50	3/4	3/4	28 1/8
	Constructing steps from Left and Right Prathakshana Mandapam to enter into the Sngunasi &c.	2	5 1/2	3'	1 1/2	57 3/4
	Parapet wall right side of Yagasalai roof	1	26	a 1 1/4	3	97 1/2
	At the entrance of top of roof	2	2	1'	1/2	9
	Total Brick in Chunam — C. ft					1033 7/8
	Deductions: -					
	Window Ways —	1	4	1'	3	18
	Balance Brick in chunam C. ft					1015 1/2

C-Stone Slabs —	Top of retaining wall round the Drain	1	104	1⅛	¼	29¼	
	Floor and covering Slabs of Drain in Prathakshana Mandapam	2	45	1¼	¼	28⅛	
	Dressing Slab one side of open space —	1	7	1¼	½	4⅜	
	Total C. ft. —						61¾
Cut stone slabs carefully dressed	Pillars for the Support of Beam stone broken in front of Namalwar —	2	1¼	1	11	27½	
	Total C. ft. —						27½
Plastering with Mortar —	Both sides of Retainingwall of Drain —	2	104	"	1½	312	
	Inside of Drain —	1	45	"	1½	67	
	Top of Drain —	1	45	3	"	135	
	Face of Parapets in the open space	1	50	"	3	150	
	Do — all round over roof	1	50	2¼	"	112	
	Front wall of Prathakshana Mandapam left of door	1	12	"	8½	102	
	Do — out side —	1	8	"	8½	68	
	Right side of door —	1	12½	"	8½	106	
	All round the platforms of Bashiachar & Namalwar	2	14	"	1	28	
	Seats of — Do —	2	7	"	½	7	
	Tops of — Do —	2	3	2	"	12	
	Side of open space in the Sugmasi Mandapam	4	4½	"	7	126	
	Steps all round	2	16	"	¾	24	
	All round the Parapets over the roof of Nagavalan	1	26	7⅛	"	185	
	All round the walls in the entrance of roof	2	5½	"	1½	16	
	Total Sqr ft —						1450
Deductions: —	windows —	2	3	"	4	24	
	Balance Plastering with Mortar					Sqr ft	1426

Teak wood Doors:-							
	Out-Side of Gurupagraham with Hooks, bolts, Nuts &c complete	1	6	4	"	24	
	Door in the Left Prakalshna Mandapam to enter into the Temple	1	6	3	"	18	
	Total Sq. ft &c						42
Jungle wood Door:-	For cook Room	1	6	3	"	18	
	Total Sq. ft &c						18
Iron Screen - Cover -	For the top of open space as an obstruction for Birds	1/5	20	6	"	120	
	Total Sq. ft &c						120
Surki Concrete:-	Floor of Drain	1	102	3	1/3	102	
	Out-side of Retaining wall	1	106	2 1/4	1/3	79 1/2	
	Floor of Verandahs in front of Yagasalai and cooking room	2	17	6 3/4	1/3	76 1/2	
	By the side of Drain in Prakalshna Mandapam	2	30	3	1/3	60	
	- Do &c - right Side for the Space of Verandah removed	2/3	1	35	6 3/4	1/3	78 3/4
	Examining the Leaky Portions over the roof & putting in with fresh Concrete	L. Sum Quantity 100					
	Total Surki Concrete C. ft &c						496 3/4
Dismantling and rebuilding the sky-Light over Yagasalai giving proper Ventilation and using old slabs		L. Sum Rs					20
- Do &c - Do &c - over Cooking Room		Lump Sum Rs					20
Provision for Iron Bars Windows (3×4) ft &c. with Frame &c Complete		(3×4)				12	12

Abstract

Items of work	Per	Rate	Quantity	Cost
Dismantling Brick and Stone walls	C.ft.	" " 4	3531	74
Excavation —	Cy.	" 2 "	10	1
Brick in Chunam	C.ft.	" 2 9	1015-7/8	175
Burnt Stone Slabs dressed	C.ft.	1 " "	61 3/4	62
Cut-Stone Slabs neatly dressed	C.ft.	2 8 "	27 1/2	69
Plastering with mortar	Sq.ft.	2 8 "	1426	36
Teak wood Doors	Sq.ft.	3 " "	42	126
Jungle wood Door	Sq.ft.	1 " "	18	18
Iron Screen Cover —	Sq.ft.	" 4 "	120	30
Surki Concrete with Plastering	C.ft.	" 2 6	496 3/4	78
— Removing and Rebuilding the Sky lights over Yagasalai	Lump Sum		Rs	20
— Do — Do — over Cooking Room	Lump Sum		Rs	20
Provision for Iron Bars with frames &c Complete —	Each	1 8 "	12	18
Total Rupees —				727
Contingencies at 5 per cent Rupees —				36
Grand Total Rupees —				763

Compared
at

23. 8. 1899

S. Vinthiya Esq

Supervisor
No. 3. Sub Division

Mus/P 6-99

order. SL 8

No 236
En 1.
D 31-8-99

An Estimate amounting to Rs 763 for repairing the Sri Lakshmi Narasimha Swami temple at Maralally, Malavalli Taluk prepared under the orders of the Mysore Superintendent is sanctioned, the charge being met from the State Grant of Rs 15000 sanctioned in Govt Pro No. 1083 dated 29th March 1899 for the repairs of Mysore Building during the Year 1899-1900.
Mus 7105-92

2. The amount sanctioned in the foregoing para will be paid on presentation to the Comptr of a bill duly signed by the Mysore Superintendent.

Mysore Secretary.

To, The Comptr to Govt with a copy of the abstract Estimate.

Copied 7. Sept. 99

MUZRAI

189 Sl 9

From

THE SECRETARY TO THE
GOVERNMENT OF MYSORE.

To

S. Krishna Iyer Esqre
Supervisor No. 3.

Dated

Despatched

Received

General No.
Muzrai F. No

Enclosure No.

D.O.

The Estimate received from You for Rs 763 for repairing the Sri Lakshmi Narasimha Swami Temple at Marahalli has been sanctioned. Enclosed is a copy of the Sanctioned Estimate ~~Kindly Please~~ put to work ~~at once and get the work~~ ~~taken up~~ at once and completed at an early date; and send a bill of actual costs to this office for payment

as soon as the repairs
are completed.

Yours.

1899 Sllo

From

S Krishna Iyer
Supervisor No: 3.
Sub Division

To

The Muzarai
Superintendent
Bangalore

Dated 29th November 1899.

Despatched ——— Do ———

Received

General No.
No.

Refer as you say

Sir, Enclosure No. 2

With reference to your D. C. Letter No. of 7th September 99, forwarding with it a Sanctioned Estimate for Rs 763, for repairing the Sree Lakshmi Narashimhaswamy Temple at Marahally, with a request to carry out the works &c, I beg to Submit herewith a Bill with its details amounting to Rs 548. 14-1. for the works done up to date by P. W. Contractor. Thanigachala Mudr, and to request that you would be so good as to Kindly pay the Amt to enable him to complete the remaining works soon.

2. I am obliged &c.

Vide no copy of 6/12.99

Received on 1/12/1899

This Bill for Payment as the Contractor is a poor Man and hard up for Money and he could not afford to wait till the works are fully completed. If ordered the Contractor will be directed to attend to your Office for Payment.

I beg to remain
Sir
Your most obedient Servant

J. Richards

Supervisor
No 3. Sub Division

No. 3 Sub Division Bill No. 1 Annual Recto Division

Repairs to Marahally Nara Simhaswamy's Temple.
Marahally Taluq. By. S.D.O. Channigarayapatna Dt. 19-11-95.

Details of work	No	Dimensions			Contents	Total of each item
		Length	Breadth	Depth		
Dismantling Brick & Stone walls:-						
Cross walls inside Sugmasi	2	3	1½	7	63	
Do. Do. outside	2	10	1½	7	210	
Side Verandah	1	10	3	3	90	
Concrete over the roof of the Ankanam Lengthwise	1	21	7½	3	472	
Retaining wall round the Drain out side of Sugmasi & Garthagriham	1	106	1½	2	318	
Covering of the Drain in the Left Prathakshina Mandapam	1	25	4½	2	225	
Verandahs between Cook Room & Brahmin Chari, Yagasalai and Nammalwar seats	2	25	6½	3	975	
Side walls of Bramhyachar	2	6¾	1½	10	202½	
Front wall of Do.	1	3½	1½	8	42	
Side walls of Nammalwar	2	6	1½	6	108	
Front wall of Do.	1	8	1¼	8	80	
Plat-forms of Nammalwar & Brahmyachar	2	10	6	1½	180	
Side wall of Verandah Room	1	10	1½	8	120	
Front walls	1	6	1½	6	54	
Walls in the Sugmasi	2	8	2½	7½	300	
Door ways in Do.	1	2½	1½	7½	28	
Broken wall at the entrance of steps leading to Top of roofs	1	1½	1	8	12	
Total Dismantling C.F.t.						3480
Excavation:-						
Foundation for the Drain to Drain off the rain water and abhishekam water from the Temple	1	15	1	2/3	10	
Total Cft.						

Brick in Chunnam:-

Retaining wall round the Drain on the Lt side of Sugnuasi	1	100	1 1/8	1 3/4	C 9
Cross wall connecting the Pillars	4	1	1 1/8	1 3/4	C 8
Filling foundation for the Drain within the Kr Rathakshna Mandapam	1	30	2 3/4	1/2	41
Out Side of — Lo 4	1	15	2 3/4	1/2	20 5/7
Side walls of Drain —	2	45	3/4	3/4	50
Covering Courses —	1	45	2 1/4	1/2	50
Platform for placing the Washingmachine	1	16	1 1/8	1 3/4	31 1/2
Front wall of Kr Rathakshna Mandapam left of entering door	1	7 1/2	1 1/8	7	59 1/16
— Lo 4 — Lo 4 —	1	4 1/2	1 1/8	1	5 1/16
— Do 4 — Ro 4 —	1	4	1 1/8	7 1/2	33 3/4
— Do 4 — Do 4 —	1	2	1 1/8	1	2 1/4
Partition walls in the Sugnuasi Mandapam	4	2	2	7	112
Seat for Swaz in — Lo 4 —	1	3	2 1/4	2 1/4	15 3/16
Breaking up the face of open space made for the light from the bottom of Roof to Top of — Do 4 —	1	42	1 1/8	3 1/2	165 3/8
— — Lo 4 — Lo 4 —	2	4	1 1/8	2	18
Constructing Steps for Left and Right of Kr Rathakshna Mandapam to enter into Sugnuasi —	2	5 1/2	3 1/2	1 1/2	57 3/4
Parapet wall Right Side of Yagasala roof	1	28	1 1/8	3	94 1/2
— — Lo 4 — Do 4 —	1	1 1/2	1 1/8	2	3 3/8
— — Lo 4 — Do 4 —	1	2	1 1/8	2	4 1/2
Seat of Dining wall to Roof Steps —	1	8 1/2	1 1/8	1 3/4	16 5/8
— Lo 4 — Do 4 —	1	8	1 1/8	4 1/4	38 1/4
— Lo 4 — Lo 4 —	1	4 1/2	1 1/4	6 1/2	36 9/16
— Lo 4 — Lo 4 —	1	4 1/2	1	1/4	1 1/8
Platform for placing the Wannialwar	1	14	1 1/8	1/2	23 5/8
Total Brick in Chunnam C ft 4 —					1086 3/8

Deductions-

Flooring Slab of Drain —	1	45	1 1/4	1/4	14 1/16
Deduction —					14 1/16

Brought forward ——— C.ft.						14 1/16
Covering Slab of Drain ———	1	45	1 1/4	1/4		14 1/16
Iron Bars Windows ———	1	4 1/2	1 1/8	3 1/2		17 11/16
Top Slabs of Both Steps ———	2	5 1/2	3 1/2	1/2		19 1/4
Total Deduction C.ft. ———						65 11/16
Balance Brick in Chunam C.ft. =	10	86	3/8	—	65 11/16	1021 5/16
Burnt-Stone Slabs Dressed:—						
Top of Retaining wall round the Drain	1	100	1 1/8	1/4		28 1/8
Floor & Covering Slabs of Drain in Prathashna Mandapam	2	45	1 1/4	1/4		28 1/8
Treading Slab one Side of Open Space	1	7	1 1/4	1/2		4 3/8
Total Burnt-Stone Slabs C.ft. ———						60 5/8
Plastering with Mortar:—						
Inside of retaining wall of Drain	1	100	1 1/2	"		150
Out-side of ——— Do ———	1	104	1 1/2	"		156
Side walls of Drain inside	1	45	"	1 1/2		67
Inside of Parapets in the Open Space	1	42	"	3 1/2		147
——— Do ———	2	4	"	2		16
——— Do ———	2	4	"	2		16
Top and out-Side of Parapet	1	42	2 1/4	"		94
Front-wall of Prathashna Mandapam Inside	1	11 1/2	"	8		92
——— Do ——— out-Side ———	1	6 1/2	"	8		52
All Round the Platforms of Bachiyachar & Vramal-wars	2	16	2 5/8	"		84
Side walls of Open Space in Sugmasi Mandapam	2	9	4 1/2	"		81
——— Do ——— ——— Do ———	2	5 1/2	2	"		22
Steps all round ———	2	16	3/4	"		24
Inside of Parapets over Vajasalai Roof	1	23	3	"		69
Out of ——— Do ———	1	26	3	"		78
Top of ——— Do ———	1	25	1 1/4	"		31
Both Sides of Cross Parapets	2	3	"	3		18
Both sides of walls at the entrance of Roof	2×2	2	"	2		16
Top of ——— Do ———	1	4	1 1/8	"		4
Face of Sea for Coping all ———	1	4	"	6 1/2		26
——— Do ———	1	8	"	4 1/4		34
——— Do ———	1	8 1/2	2	"		17
Inside of ——— Do ———	1	8 1/2	2	"		17
——— Do ——— ——— Do ———	1	8	1 3/4	"		14
End of ——— Do ———	1	2 1/2	1 1/8	"		3
Top of ——— Do ———	1	18	1 1/8	"		20
Carried over						13

Brought forward Sq. ft.

All round the Seat of Alwar in Lingumasi	1	5	a	3	
Sides of Door	2	6	1/4	a	6
Do.	2	6	1	a	6/2
Sides of window	2	4	1	a	8
Side & Top of Do.	2	4½	1	a	9
Do. of Doors	2×2	3½	1½	a	21
Cornice with open space	2	10	1	a	20
Top of Parapet with open space	2	4	1¼	a	10
Total Plastering Sq. ft.					14.58

Deductions:—

Both Sides of window	2	3½	a	4½	31
Balance Plastering Sq. ft.					14.27

Surki Concrete:—

Out Side of Retaining wall round the Drain	1	22	5	⅓	36⅔
Do. Do.	1	19	4½	⅓	28½
Do. Do.	1	27	8¼	⅓	74¼
Do. Do.	1	21	6¼	⅓	43¾
Do. Do.	1	27	5	⅓	45
Do. Do.	1	20¼	10	⅓	67½
Floor of open space	1	12	3½	⅓	14
Do.	1	7½	2	⅓	5
Cusine of Lingumasi	1	12	11	⅓	44
Platform of Bashiachar & Namaluar	2	6½	5¼	⅓	22¾
Verandah in front of Magazeen	1	17	6	⅓	34
All round the Parapet in the open space of the roof	1	42	¾	⅓	10½
Total Surki Concrete C. ft.					425

Iron screen Piers for the top of open space to an obstruction for Birds &c	1	18	5½	a	99
Total Sq. feet					99

Teak wood Door:—

Out side of Kirbegraham with Hooks, Bolts, Intake complete	1	6	4	a	24
Total Sq. ft.					24

Dismantling the old Sky Light & Magazeen proof & rebuilding a new one, giving proper Ventilation — Lump Sum Rs. 20.

Do. Do. over Cooking Room — Lump Sum Rs. 20.

(Sd) N. Venkatanatha Iyer
Sub Overseer.

(Sd) J. Robinson
Supervisor
No. 3. Sub Division

MUZRAI

189

From The Muzrai Supdt

To

The Commr & Govt.

Dated 4. 12. 99

Despatched 5th

Received

General No. 579

Muzrai F. No. 6-99.

Enclosure No. -1.

Govt Ord No. 236 dated 31st August 1899, sanctioning an estimate for Rs 763 for repairing the Sri Lakshmi Narasimha Swami temple at Maralli, Malvalli Taluk.

Adverting to para 2 of the above, has the honor to forward herewith a duly countersigned measurement list for Rs 548-14-7 on account of work done up to 29th Nov 1899

and to request that
the measurement bill
in question may be duly
audited and returned
to this office, ~~for payment~~. the amount being made
payable at ~~that~~ the ~~Peabody~~ Talbot Treasury, Easton where the Temple
is situated.

~~Deputy~~ Superintendent

Mark Bill.

L.O

To S. Krishna Iyer Esq
Superintendent
Madura

Note Office
Memo D.O. enclosure.
To be sent duly
registered & paid
for acknowledgment

Copied
21st Dec 1899

Sl 12

I am in receipt
of your letter of the
2 & the 11th forwarding
measurement
& bill amt. to Rs.
5 4 0 - 14 - 1 due to
the contractors on account
executed
of the repairs to the
Sri-Vaikuntham
Irrigation Channel.

I herewith return
the bill duly audited
& the Comp.s for payment
at Srivaikuntham
Taluk Treasury.

~~A Receipt Endorsed~~
~~on~~.

Please keep the
Money ready to be paid to the
Contractor.

MUZARAI.

GUMBUZ.

189

From

Officer in charge of the Gumbuz,

Srirangapatam.

To

Dated

Despatched

Received

Enclosures No.

General No
Muzarai F No

I have made an Endorsement on the bill for payment of the money to you. Messrs. Broadley have the Money paid to the Contractors & send me his Receipt. Stamped for record in this Office.

~~I transfer this bill~~
~~to Mr Kirby to receive the~~
~~Gumbuz~~ Krw Werks to remain
~~Gumbuz~~ works.
~~Cannot be credited~~ will be credited
~~Cannot be credited~~ early.

Approved

A1

No 3 C. I Department

Mandya & Malvally Talugs

SL13

No: 3. Sub-Division D.P.W.
Mandya.

No: 89/2

The Huzarai Superintendent of
Mysore.

Sir,

I beg to submit herewith for payment the final bill Amounting to Rs 229-13-4 for the works done by Contractor Thanniachalam Moodliar to Temporally Sree Lakshmy Narasimha Swamy's Temple and to state that all the works estimated for, have been Satisfactorily Completed.

It would be seen from the bill that the Sanctioned Amount of Rs 763 has been slightly exceeded by Rs 15-11-5 which is chiefly due to fixing two ornamental pillars in front of Thayar Sannathi.

I beg to remain
Sir,
Your Most obedient servt.
V. S. Narasimhiah
Superintendent

Mandya
dated 8/2/1900

OFFICE OF THE DEWAN OF MYSORE
RECEIVED
Date 9.2.1900
No. 548
HUZRAI BRANCH

Submitted for orders
8/2/1900

No 3. Sub Division

Mandya & Malvally Talugs

Bill No 2:- By Contractor Thanigachala Mudr Dated 29/12/1899.

Repairs to Marahally Sree Lakshmee Narasimhaswamy's Temple.

Malvally Talug.

No	Dimensions L	B	D	Contents	Remarks.
					Dismantling Brick and Stone walls:-
					Total Measurements taken:-
2	3	1½	7	63	Cross Walls inside of Sungumasi Mandapam.
2	10	1½	7	210	—— Dº —— Inside.
1	10	3	3	90	Side Verandah
1	21	7½	3	472	Concrete over the Roof of one Angamam Lengthwise.
1	106	1½	2	318	Retaining Wall round the Drain out Side of Sungumasi and Girpagraham Covering of the Drain.
1	25	6	2	300	Left Pradakshina Mandapam
2	25	6½	3	975	Verandah between Cook Room & Bashiyachar Jaga - Salai and Nammalwar Seat.
2	6¾	1½	10	202½	Side walls of Bashiyachar
1	3½	1½	8	42	Front of —— Dº ——
2	6	1½	6	108	Side Walls of Nammalwar.
1	8	14	8	86	Front Wall of — Dº —
2	10	6	1½	180	Platform of Bashiachar and Nammalwar
1	10	1½	8	120	Side Walls of Verandah Rooms
1	6	1½	6	54	Front wall
2	8	2½	7½	300	walls in the Sungumasi
1	2½	1½	7½	28	Door ways in - Dº —
1	1½	1	8	12	Entrance of steps leading to top of Roof.
Total		C ft	—	3555	Total Dismantling
					Excavation foundation for the Drain & Drain of the rain water and Abishekam Water from the Temple
1	15	1	⅔	10	Excavation
	Total	Cft		10	of —— Dº ——

Brick in Chunnam:-

1	100	1 1/8	1 3/4	196 7/8	Retaining wall out Side of Sugunasi.
4	1	1 1/8	1 3/4	7 7/8	Cross walls Connecting the Pillars.
1	30	2 3/4	1/2	41 1/4	Filling foundation for the Drain within the Prathakshna Mandapam.
1	15	2 3/4	1/2	20 5/8	out Side of - Do
2	45	3/4	3/4	50 5/8	Side walls of Drain
1	45	2 1/4	1/2	50 5/8	Covering Courses.
1	16	1 1/8	2	36	Platform for Placing the Bashiyachar
1	14	1 1/8	2	31 1/2	— Do — for Nammalwar
1	7 1/2	1 1/8	7 1/2	63 1/4	Front-wall of Prathakshna Mandapam left of entering Door:-
1	4 1/2	1 1/8	1	5 1/16	
1	4 1/2	1 1/8	7 1/2	38	
1	2 1/2	1 1/8	1	2 13/16	
4	2	2	7	112	Partition walls in the Sugunasi Mandapam
1	3	2 1/4	2 1/4	15 7/16	Seat for alwar in the Sugunasi Mandapam.
1	42	1 1/8	3 1/2	165 3/8	Backing the face of open Space made for the light- from the bottom of roof & Top of Roof
2	4	1 1/8	2 1/4	20 1/4	— Do — — Do —
2	5 1/2	3 1/2	1 1/2	57 3/4	Constructing Steps for Left & Right of Prathakshna Mandapam to enter into Sugunasi
1	28	1 1/8	3	94 1/2	Parapet-wall right-side of Yagasalai roof
1	1 1/2	1 1/8	2	3 3/8	— Do — — Do —
1	2	1 1/8	2	4 1/2	— Do — — Do —
1	8 1/2	1 1/8	1 3/4	16 5/8	Scaffolding wall to Roof steps
1	8	1 1/8	4 1/4	38 1/4	— Do — — Do —
1	4 1/2	1 1/4	6 1/2	36 9/16	— Do — — Do —
1	4 1/2	1	1/4	1 1/8	--- Do — — Do —
1	5 1/2	1/2	1/2	1 3/8	Parapet-wall in front of Prathakshna Mandapam
1	1 3/4	1 3/4	1/2	1 1/2	— Do — — Do —
1	5 1/2	1/2	1/2	1 3/8	
1	7 3/4	1 1/8	1/2	4 3/8	— Do — — Do —
1	4	1 3/4	1/4	1 3/4	— Do — — Do —
1	2	1 1/8	1/4	9/16	— Do — — Do —
1	5 3/4	3/4	2 1/4	9 11/16	— Do — — Do —
Total Cft —				1130 7/8	of Brick work:—

		B. forward		1130 5/8	C.ft. Deductions:-
2	45	1 1/4	1/4	28 1/8	floor and covering Slabs of Drain
1	4 1/2	1 7/8	3 1/2	17 11/16	Window ways.
2	5 1/2	3 1/2	1/2	19 1/4	Top Slabs of both steps
	Total	C.ft.		65 1/16	
	C. feet	=		1065 5/16	Balance Brick work
Deduct- the quantity Paid Vide Bill No. 1 Dated 19-11-23 C.ft. 102 5/16 of brickwork					
	C. feet	=		(44)	Balance now to be Paid = 1065 5/16 - 102 5/16 = 44 C.ft.
					Burnt Stone Slabs dressed.
1	102	1 1/8	1/4	28 11/16	Coping Slabs over retaining wall
2	46	1 1/4	1/4	28 3/4	Floor and Covering Slabs of Drain.
1	7	1 1/4	1/2	4 3/8	Treading Slab one Side of open Space.
				61 3/4	Total C.ft.
					Deduct the quantity Paid Vide Bill No. 1 D. 19-11-23 60 5/8 C.ft.
	C.	ft.		1 3/16	Balance to be Paid = (61 3/4 - 60 5/8 = C.ft. 1 3/16)
					Cut Stone Slabs neatly dressed.
1	1 1/8	1	10	11 1/4	Supporting Pillar for the broken beam in front of Nammalwar.
	X Total	C.ft.		11 1/4	of Cut Stone work
					Plastering with Surki mortar:-
1	100	-	1 1/2	150	Inside of Drain: Retaining wall
1	104 1/2	"	1 1/2	157	out of ——— Do. ———
2	45	"	3/4	68	Side walls of Drain
1	42	"	3 1/2	147	Inside of Parapet in the open Space
2	4	"	2	16	——— Do. ——— Do. ———
2	4	"	2	16	——— Do. ——— Do. ———
1	44	"	2 1/2	110	Cut Side and Top of Parapet walls.
1	11 1/2	"	8	92	Inside of Front wall of Prathakshina Mandapam.
1	6 1/2	"	8	52	——— Do. ——— Do. ——— out Side.
2	16	"	2 3/4	88	All Round the platforms of Bashiachar & Nandi- war.
2	9	4 1/2	"	81	Side walls of open Space in the Sugunasi Mandapam.
2	5 1/2	2 1/2	"	27	——— Do. ——— Do. ———
1	23	"	3	69	Inside of Parapet over Nagaabarai Roof
1	26	-	3	78	out side of ——— Do. Do.
				1151	Total carried over.

					1157.	Brought forward
1	28	1/4	"		31	Top of Parapet over Agasali Roof
2	3 1/2	"	3		21	Both sides of Cross parapets
2x2	2	"	2		16	——— Do. ——— of walls at the entrance roof
2	2	1/8	"		5	Top of ——— Do. ———
1	4	"	6 1/2		26	face of Scafolding wall
1	8	"	4 1/2		36	——— Do. ———
1	8 1/2	"	2		17	——— Do. ———
1	8 1/2	"	2		17	Scafolding wall inside
1	8	"	1 3/4		14	——— Do. ———
1	2 1/2	1/8	"		3	End of ——— Do. ———
1	18	1/4	"		22	Top of ——— Do. ———
1	5	"	3		15	All round the Seat of Alwar in the Sanctum
2x3	6	1/4	"		45	Sides of door.
2x3	6	1	"		36	——— Do. ———
2	4	1	"		8	Sides of Window.
2	4 1/2	1	"		9	Sill + Top of ——— Do. ———
2x2	3 1/2	1 1/2	"		21	Sill + Sop of Bars
2	4	1 1/2	"		12	——— Do. ———
2	10	1	"		20	Cornice in the open space.
2	4	1/4	"		10	Top of Side Parapet in the open Space.
1	5 1/2	1	"		6	Front Parapet over Prathakshanam and pam Roof
1	5 1/4	1	"		5	——— Do. ——— ——— Do. ———
1	73/4	1 1/2	"		11	——— Do. ——— ——— Do. ———
1	2	1 1/2	"		3	——— Do. ——— ——— Do. ———
1	1 3/4	1 3/4	"	3		——— Do. ——— ——— Do. ———
4	1 3/4	"	1/4		2	——— Do. ——— ——— Do. ———
1	6 1/2	"	2 1/4		15	——— Do. ——— ——— Do. ———
1	5 3/4	"	2 1/4		13	——— Do. ——— ——— Do. ———
1	5 3/4	"	1		6	——— Do. ——— ——— Do. ———
Deductions:-					15.95	Total Sqrs.
2	3	"	4 1/2		31	Both sides of windows.
	Balance Sqrs.				15.68.	Deduct the Quantity Vide Bill Dt. D 19/11/29 = Sqrs 14.27
Balance to be paid Sqrs					1.41	Balance due Paid = 15.68 − 14.27 = Sqrs 1.41

wood Doors.

			24		nt Side of Girpagrahan with hooks, bolts & nuts &c complete.
6	3	"	18		in the Left Parathakotma Mandapam & enter into the Temple.
2ot			" 42		of Teak wood
			ft 24		Deduct the Quantity Vide Bill No 1 D 19-11-99.
			ft 18		Balance Sqr. feet = 42-24 = 18 Sq. ft
					gle wood Door for Cook Room.
— 1	6	3	"	18	Honnai Tree. for Cook Room.
—			Sq	18	of Honnai wood.
					Iron Bars Window left of Big Door with frames &c.
1	3	"	4	12	Sq. feet. Complete.
			ft 12		of Iron Bars window.
					Surki Concrete:-
1	22	5¼	⅓	38½	Out Side of retaining wall round the Drains
1	19	4½	⅓	28½	—— Do —— —— Do ——
1	27	8½	⅓	76½	—— Do —— —— Do ——
— 1	21	6½	⅓	45½	—— Do —— —— Do ——
1	27	5¼	⅓	47¼	—— Do —— —— Do ——
1	20	6½	⅓	70	Do —— — Do ——
— 1	12	3¾	⅓	15	—— Do —— —— Do ——
1	7½	2	⅓	5	Floor of open space of — Do —
1	12	11	⅓	44	Inside of Sugumasi
2	7	5¼	⅓	24½	Platformno of Bashniachar & Namalwar
1	17	6	⅓	34	Verandah in front of Yagasalai
1	29	1	1½	43½	All round the Parapets in the open space of the Roof
1	15	¾	1½	16⅞	—— Do —— —— Do ——
1	28½	½	1½	21	All round the Sky light of Yagasalai.
1	32	½	1½	24	—— Do —— Cooking Room
	2Total		ft 534		of Surki Concrete.
			425½		Deduct the previous Quantity Vide Bill No 1 D 19-11-99
	alance		ft 108½		Balance to be Paid = 534½ - 425 11/12 = 108 7/12 C. ft
1	18	5½	"	99	Screen cover for the Top of Open space as an abstruele for Birds &c.
	2otal	C			

is mantling the old Sky light over the roof of
alai and Rebuilding a new one giving proper
Venkilatio

Do — over Cooking Room.

J. Smn 20

L Smn 20

Extra works done as per orders of Sub Divl Officer.

Drain on Side of Prathakshanamandapam

1	12	3/4	3/4	6 3/4	Excavation.
1	10	1 1/2	1/6	2 1/2	do
1	9	2/3	1/3	2	do
1	10	1	3/4	7 1/2	do
	Total C.F.			18 3/4	C.F. Excavation.

Brick in chunnam:—

1	30	2 3/4	1/2	41 1/4	Filling foundation
2	30	3/4	3/4	33 3/4	Side walls of do
1	30	2 1/2	1/2	37 1/2	Covering Courses
	Total C.F.			112 1/2	C.F. Brick in Chunnam.

Deductions.—

2	30	1 1/4	1/4	18 3/4	Floor & covering Slabs of Drain
	C.F.			93 3/4	Balance C.F. = 112 1/2 - 18 3/4 = 93 3/4 C.F.

Burnt Stone Slabs dressed:—

2	30	1 1/4	1/4	18 3/4	Floor & covering Slabs.
	Total C.F.			18 3/4	C.F. do

Plastering with mortar.—

2	30	"	3/4	45	Inside of Side walls of Drain
	Total S.F.			45	S.F. Plastering.

Iron Screen Covers for both Sides of opening

Brick in chunnam:—

2	5	1 1/8	1 1/2	16 7/8	Lengthwise walls
1	4	1 1/8	1	4 1/2	Cross wall
2	5	1 1/8	1 3/4	19 11/16	Lengthwise walls
1	4	1 1/8	1	4 1/2	Cross wall
	Total C.F.			45 9/16	C.F. Brick in chunnam.—

Plastering with mortar

2x2	3 3/4	"	1 1/2	22	Lengthening wall
1	4	1 1/4	"	5	Cross wall
1	13	1 1/4	"	16	Top all around
				43	Total carried over

asd:

4			8	engthening wall
1		1	6	Cross wall
6	×	1	6	—— Do ——
4	1¼	×	17	Top all Round.
		"	1:00	of Plastering:-
2	4	3 ×	24	Iron Screen Cover for the open space at the Sides.
		e. =	24	

oving & placing the ornamental 2 Pillars on both sides of Door ways of Goddess Temple:

8 5- Each for 2 = Rs 10.

9

10

Constructing a Kettai-Chimney over Roof of Building in places of Old ones Broken & fallen & the chimney Plastering all around Right-Side.

8	13 × 1 × 1)	8		Erecting the above - Each @ annas 8 = 4-0-0
11	1 4 × 2 × 1)	11	—— Do ——	- Left each @ 8 annas. = 5-8-0
	4 × 1	4	—— Do ——	Front each @ 8 annas. = 2-0-0
		23		11-8-0
10	13 × 1	10	Old ones Repairing each @ 4 annas. =	2-8-0
1	1 4 × 1 2 × 1)	1	one —— Do ——	—— Do —— = 0-4-0

White-washing the Mandapam over Theronam & over & Main Building:-

4 each @ annas 8 = 2-0-0.

(SS) N. Vaithianatha Iyer
Sub Overseer

Dy. 31st January 900

J. Vis, Annamalai.

Superviser:
Dy 3. Sub Division



No: 3 Sub-Division office
D. P. W
Bandya.

The Muzarai Superintendent
Bangalore.

10-1-1900

Camp Malavelly dated 8th January 1900.

Sir,

I beg to acknowledge with thanks the receipt of your D. O. letter dated 21st ultimo, with the bill for Rs 548-14-1 for the works done to Sree Narasimaswamy's temple at Maravally, duly audited by the Comptroller and to enclose herein the stamped receipt for the said Amount duly signed by the Contractor, for the payment made to him today.

2. The works for the temple as estimated for, have been Completed Satisfactorily, and the final bill for the same will be submitted so as to reach your office by the 15th instant, and in Conclusion.

I am happy to be able to report that, by the works just carried out there is now ample light and ventilation in the temple so much so, one could see the Darby Sree Narainswamy from the very first entrance of the temple.

I beg to remain
Sir,
Your most obedient Servant
S. Srinivasa Ch
Supervisor No 3.
Sale. Division

A.H.

Enclosure. 1. Receipt for Rs 548-14. 1.

No 892 Enc 1
Dy Dated 31-12-1900

Sl 16

Read:-

Govt-Pro. No 236
Dy 31st Augt 1899

Sanctg an Estimate for Rs 763 for repairing the Sri Lakshmi Narasimha Swami Temple at Mattehalli, Malavalli Taluk

Order thereon.

The repairs Sanctd to the temple have been Completed at a cost of Rs 11-5 or Rs 15-11-5 more than the Amount Sanctd.

balance due to the Contractor in final adjustment of the actual cost of the repairs including the excess outlay Sanctd in the foregoing para is now Countersigned and forwarded to the Comptr for audit. And refund of this Office for payment.

It is requested that the Bill may be returned to the Munsif for payment when Audited by the Comptr

In Malavalli Taluk Treasury -

Under-Secy

To The Comptr & Auditor

of the Sanctioned
Estimate - This ~~exceeds~~ adds
~~expenditure~~ outlay
of Rs 15-11-5 in Sanctd.,
the Charge being
debited to the State
Grant, provided
in the current year's
Municipal Budget.

2 - A measurement
Bill for Rs 5260-14-1.
in respect of the Upkeep repairs executed to a temple
has been already planned in
this office Docket I
Comp. no 529 of the
4th Dec 1899. And
a further measurement
Bill amtg. to Rs
22.9-13-4, ~~the~~ (the

Copied 28.3.00

Sl 15

To,

S. Krishna Iyer Esqre.
Supervisor. D. P. Wks.
Mandya.

Office Note.

The D-o and enclosure to be heard duly registered and paid for acknowledgment.

D. O

I am in receipt of your letter No. 89/2 dt 8th February 1900 forwarding a final measurement bill for Rs 229-13-4 due to the Contractor on account of the repairs executed to the Sri Narasimhaswami temple at Maradalli

I herewith return the bill duly audited by the Comptroller for payment in the Mulabagal Taluk Treasury and I have also made an endorsement on the bill for payment of the money to you. Please have the money paid to

to the contractor and send me his stamped receipt for record in this office.

Yours.

Gen. 31.]

~~189~~ 1900 Sl 16.

From S. Krishna Iyer
Supervisor W.P.W.
Mandya.

To The Munsari Serperin
Bangalore



5-4-1900

Dated Mandya dated 1st April 1900
Despatched 2/4/900
Received

General No. 95
No.

Enclosure No. 1 Receipt.

Sir,

I beg to forward herewith a receipt for Rs 225-13-4 for Repairing the Sri Narasimha Swamy's temple already stamped and Signed by Contractor Thammiachalam Moodliar as requested in your D.O. dated 28th March 1900.

I beg to remain
Sir
Your most obedient Servant
S Krishna Iyer

Supervisor in
Sole Dri

P W. 7 A

(Counterfoil.)

No. 4/1

Dt 31.3.900

Payee P W Thanniachalam Mudaliar

Amount 229 — 13 — 4

Name of work Repairing the Maralally Sri Narasimma-Swamy's Temple at-Maralally

Witness A Hmain

ಸಾಕ್ಷಿಗಳು

Truce Rolls Division

ಡಿವಿಜನ್

No. 4/1

ನಂ.

Date 31.3.900

ತಾರೀಖು

Received from The Amuzari Superintendent of Mysore Through The Supervisor No 3 Cole Division Mandya

ಇಂದತೆಗದುಕೊಂಡ

the sum of Rupees Two Hundred and Twenty Nine, Annas Thirteen and pies four only

ಪೊಬಲಗು ರೂಪಾಯಿ

on account of Repairing the Maralally Sri Narasimma-Swamy's Temple at-Maralally

ಕಿರ್ಚಿದ

Witness A Hmain

ಸಾಕ್ಷಿಗಳು

N.B —The payees should add, in their own handwriting and language, words "as a final payment in settlement of all demands" (ಎಲ್ಲಾ ಬಾಕಿಗಳ ಅಖೈರುನೈಸಲಿಗಾಗಿ.)

2 In the case of payees who can neither read nor write, their mark or seal should be attested by two competent witnesses, in whose presence the nature of the payment should be fully explained.